

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

533
East
1/2-1
0.822 mi.
4338 ft.

PRIVATE RESD
2966 BRIGHTON 5TH ST
BROOKLYN, NY

NY Spills S112228715
N/A

Relative:
Higher

Actual:
9 ft.

SPILLS:

Name: PRIVATE RESD
Address: 2966 BRIGHTON 5TH ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1208538 / 2013-11-17
Facility ID: 1208538
Facility Type: ER
DER Facility ID: 425872
Site ID: 471601
DEC Region: 2
Spill Cause: Storm
Spill Class: D6
SWIS: 2401
Spill Date: 2012-11-02
Investigator: TJDEMEO
Referred To: Not reported
Reported to Dept: 2012-11-02
CID: Not reported
Water Affected: Not reported
Spill Source: Private Dwelling
Spill Notifier: Other

Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2012-11-02
Spill Record Last Update: 2013-11-17
Spiller Name: NOEL
Spiller Company: PRIVATE RESD
Spiller Address: 2966 BRIGHTON 5TH ST
Spiller Company: 999
Contact Name: NOEL
DEC Memo:

"11/02/12-Responded to the site, nobody was at home. Left business card requesting to contact DEC.(Hassan Ahmed) 11/17/13 TJD Site inspection - Hurricane Sandy follow-up. Vacant property - for sale sign out front. No stains or petroleum odors noted exterior to structure. No visible fill or vent pipe was observed. No interior/basement access was available. Interview with (2) area residents - both unaware of any petroleum spill at property and have been residents of adjacent structures both pre and post Hurricane Sandy. Neighbor at 425 Oceanview Avenue (Ryan Forester) states he was inside property following sandy and observed only flood damage - no petroleum impacts observed. He further reports that the owner of property has relocated - a contractor was observed removing debris from basement following storm. Second neighbor (Arthur Gensin) states he recently toured the property as a potential purchaser and did not observe any petroleum odors - only mold damage. Based upon inspection findings and statements made by neighbors no further action is required. Spill administratively closed."

Remarks: "Basement tank leaked into basement. Cleanup is underway."

All Materials:

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Site ID: 471601
Operable Unit ID: 1221457
Operable Unit: 01
Material ID: 2220102
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 100.00
Units: G
Recovered: Not reported
Oxygenate: Not reported